




The State of New Hampshire
Department of Environmental Services



Michael P. Nolin
Commissioner

November 3, 2005

Mr. William Vardaro
21 Farmhouse Road
Bedford, NH 03110

Re: 36 Oakdale Road, Bradford, NH

Dear Mr. Vardaro:

On November 2, 2005 personnel from the Water Division ("the Division") received a site assessment of your property on Oakdale Road in Bradford, conducted by Robert Stewart, Jr., a licensed septic designer. That assessment clearly found both a septic tank and a dry well, acting as a leaching system, on the property. The purpose of submission of this site assessment was to demonstrate that your property is served, and has been served, by more than a holding tank. This investigation was to determine compliance with RSA 485-A:29, I and applicable rules promulgated pursuant thereto, and specifically whether the deficiencies noted in our letter of deficiency have been corrected.

As a result of receipt of this information, it was determined that the deficiencies noted in our letter of October 26, 2005 have been corrected.

Thank you for your cooperation in remedying this situation.

If you have any questions regarding this letter, please contact Richard de Seve at (603) 271-3442.

Sincerely,


COPY

William E. Evans, P.E.
Administrator
Subsurface Systems Bureau

WEE/RJD

cc: James Falicon, Supervisor, SSB, DES
Gretchen Hamel, Administrator, DES Legal Bureau ✓
Board Of Selectmen, Town of Bradford
Richard J. de Seve, SSB, DES